



Forrester Manufacturing Co., Inc.  
5073 Bristol Industrial Way  
Buford, GA 30518  
Toll Free 866-256-4499

Project Title \_\_\_\_\_

03 3000-1  
Cast-in-Place Concrete

## SECTION 03 3000

### CAST-IN-PLACE CONCRETE

#### PART 1 - GENERAL

##### 1.01 SUBMITTALS

###### A. Shop drawings:

1. Column block-outs; stay in-place: Indicate size, configuration and quantity. Shop drawings to be prepared by Forrester Mfg Company, Inc., 5073 Bristol Industrial Way, Buford, Georgia 30518. Phone: 866-256-4499.

#### PART 2 - PRODUCTS

##### 2.01 MATERIALS

###### A. Formwork:

1. Column block-outs; stay in-place:
  - a. Product standard of quality: Forrester Mfg Company, Inc., 5073 Bristol Industrial Way, Buford, Georgia 30518; Pocket-Form Isolator. (866) 256-4499.
  - b. Characteristics:
    - 1) Material: High content recycled high density polyethylene, HDPE, multi-piece integrally reinforced stay in-place form.
    - 2) Size: As required by column base plate size and depth of column footing below finish slab elevation.
    - 3) Accessories; furnish:
      - a) Locking Lift Brackets (LLB's) for complete installation.
      - b) Flush fitting removable safety cover meeting OSHA safety requirements. (for 24" and or 28" square units only.)

#### PART 3 - EXECUTION

##### 3.01 INSTALLATION

###### A. Forms:

1. Column block-outs; stay in-place:
  - a. Install stay in-place forms at columns at grade on footing in accord with manufacturer's installation instructions.
  - b. Use Locking Lift Brackets (LLB's) to level form top to finish slab level; secure form to footing.
  - c. Install safety cover over completed pocket form installation immediately.
  - d. Leave form in place after concrete pour; remove safety cover just prior to casting. Clean form void interior of deleterious material prior to casting.

**END OF SECTION 03 3000**